

Chip Minimizer

PROTECT THE BEAUTY

The most common countertop service calls are to repair chips found along a sink's edge. These repairs generally cost \$400 – \$600. By simply choosing a 4.5x lower profile, rounded edge around a sink you can avoid these costly repairs and keep your stone looking flawless. Only available on Quartz & Natural Stone.

BENEFITS

- Provides an added layer of impact resistance
- Less fear of heavy pots and pans causing a chip
- Adds a finishing touch and enhances your sink design
- Complements any style sink

